

VEOLO firmware upgrade guide

There are two methods to upgrade the firmware of your VEOLO.

Under normal circumstances, it is recommended to use the normal SYSTEM UPGRADE method. In any event of system corruption and a normal system upgrade is not possible; please use the RECOVERY UPGRADE method instead.

Please contact technical support at techsupport@acryan.com should you require further assistance.

NOTE: Please do not power off the unit during the flashing process.

=====

SYSTEM UPGRADE method (Recommended)

1. Copy both files in the downloaded package, “**update_app.zip**” and “**update_system.zip**” to the root directory of a USB flash drive and connect it to any USB host port of VEOLO.
2. Enter the Settings page, followed by Misc and then to System update and select “Update from USB/SD Card”.
3. Continue to provide the location of the upgrade package. A message will shortly appear to prompt for upgrade when the necessary files are found in the selected location. Click **Ok** to continue.
4. The unit will reboot and start to upgrade. During upgrading it is common for the unit to reboot once or more.

=====

RECOVERY UPGRADE method

1. Copy both files in the downloaded package, “**update_app.zip**” and “**update_system.zip**” to the root directory of a USB flash drive and connect it to any USB host port of VEOLO.
2. Switch off the main power to the unit.
3. Press and hold on to the power button on the side of the unit.
4. Switch on the main power.
5. Release the power button when the upgrading process is seen started on your display in a moment.
6. During upgrading it is common for the unit to reboot once or more.

=====

FIRMWARE CHANGE LOG

New Features / Improvements / Bug Fixes

Model: AC Ryan VEOLO ACR-VE91200
Version: Version.1.0.0.849.VEOLO
Release: 2011-12-12

Version.1.0.0.849.VEOLO

1. Fix device keyboard "Auto-cap" to operate correctly according to application environment
2. Fix issue for cut and paste files
3. Fix certain video playback unable to display in full screen
4. Fix unable to mount SAMBA folder when the server response is slow
5. Fix unable to start DHCP process when the Ethernet cable is unplugged and then re-plugged
6. Fix certain videos unable to pause
7. Fix subtitle size changes when playing back various videos with different resolution
8. Fix unplugging the default storage will cause a system reboot
9. Fix unable to sort by Name/Size/Time modified in File Manager when certain menu language is used
10. Fix SAMBA server may disconnect when large files are copied over to a FAT32 formatted storage
11. Fix storage locations correctly displayed as NAND, SDCard and USB when viewed from a SAMBA client
12. Add Android Marketplace application
13. Add support for retaining user data and applications during firmware update
14. Add support for HTML5 video tags (MPEG-4, H.264, Ogg Theora)
15. Add support for HTML5 audio tags (PCM, MP3, Ogg Vorbis)
16. Add support for German QWERTZ keyboard
17. Add new desktop wallpapers
18. Add "Input method and keyboard" during initial setup process
19. Add caption in File Manager for the 3 function buttons to switch layout/media filter/sort view
20. Add blinking effect on the front panel LED when firmware update is in progress
21. Add Online upgrade feature for new firmware releases
22. Improve IDX/SUB subtitle display
23. Improve PGS subtitle display
24. Improve various OSD menu language errors
25. Improve PNG format decoding
26. Improve SAMBA server data transfer speed
27. Improve problem of Flash player video frame that remains fixed in position when scrolling up/down or when exiting a playback frame
28. General improvement to Flash player performance
29. General improvement to video and image decoding
30. General improvement to system stability, fix various system crash
31. Default "Keep aspect ratio" to Letterbox

Version.1.0.0.627.VEOLO

Initial firmware release

NOTE: The initial firmware will erase all previously installed apps.